

| | | | | | | | | | | | | | | | | | | | |
|--------------|-------------|-----------------------|---|---|---|---|---|---|---|---|----|--|--|--|--|--|--|--|--|
| MHDD 0001 | Mar 2013 | 766432mE 7552941mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | NA | | | | | | | | |
| MHDD 0002 | Mar 2013 | 766405mE 7553004mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | NA | | | | | | | | |
| MHDD 0003 | Mar 2013 | 766483mE 7552968mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | NA | | | | | | | | |
| MHDD 0004 | Mar 2013 | 766536mE 7553017mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | NA | | | | | | | | |
| MHDD 0005 | Mar 2013 | 760866mE 7554801mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | NA | | | | | | | | |
| MHDD 0006 | Mar 2013 | 760866mE 7554801mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | NA | | | | | | | | |
| MHDD 0007 | Mar 2013 | 760866mE 7554801mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | NA | | | | | | | | |
| MHDD 0008 | Mar 2013 | 760886mE 7554706mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | NA | | | | | | | | |
| MHDD 0009 | Mar 2013 | 760886mE 7554706mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | NA | | | | | | | | |
| MHDD 0010 | Mar 2013 | 761943mE 7552979mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | NA | | | | | | | | |
| MHDD 0011 | Mar 2013 | 761849mE 7553098mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | NA | | | | | | | | |
| MHDD 0012 | Mar 2013 | 765050mE 7554050mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | NA | | | | | | | | |
| MHDD 0013 | Mar 2013 | 764177mE 7551451mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | NA | | | | | | | | |
| MHDD 0014 | Mar 2013 | 766238mE 7552929mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | NA | | | | | | | | |
| MHDD 0015 | Mar 2013 | 760902mE 7554549mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | NA | | | | | | | | |

| | | | | | | | | | | | | | | | | | | | |
|--------------|------------------------|-----------------------|---|---|---|----|---|---|--|---|----|--|--|--|--|--|--|--|--|
| MHRC 0016 | Apr 2017 | 760900mE 7554510mN | ✓ | ✓ | ✓ | NA | ✓ | ✓ | | ✓ | NA | | | | | | | | |
| MHRC 0017 | Apr 2017 | 760897mE 7554601mN | ✓ | ✓ | ✓ | NA | ✓ | ✓ | | ✓ | NA | | | | | | | | |
| MHRC 0018 | Apr 2017 | 761008mE 7554510mN | ✓ | ✓ | ✓ | NA | ✓ | ✓ | | ✓ | NA | | | | | | | | |
| MHRC 0019 | Apr 2017 | 760815mE 7554602mN | ✓ | ✓ | ✓ | NA | ✓ | ✓ | | ✓ | NA | | | | | | | | |
| MHRC 0020 | Apr 2017 | 766180mE 7552906mN | ✓ | ✓ | ✓ | NA | ✓ | ✓ | | ✓ | NA | | | | | | | | |
| MHRC 0024 | Apr 2017 | 764928mE 7554057mN | ✓ | ✓ | ✓ | NA | ✓ | ✓ | | ✓ | NA | | | | | | | | |
| MHRC 0026 | June 2017 | 766364mE 7552942mN | ✓ | ✓ | ✓ | NA | ✓ | ✓ | | ✓ | NA | | | | | | | | |
| MHRC 0027 | June 2017 | 766400mE 7552945mN | ✓ | ✓ | ✓ | NA | ✓ | ✓ | | ✓ | NA | | | | | | | | |
| MHRC 0028 | June 2017 | 766185mE 7552860mN | ✓ | ✓ | ✓ | NA | ✓ | ✓ | | ✓ | NA | | | | | | | | |
| MHDD 0021 | April/ May 2017 | 761924mE 7552975mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ | NA | | | | | | | | |
| MHDD 0022 | April/ May 2017 | 761753mE 7553150mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ | NA | | | | | | | | |
| MHDD 0023 | April/ June 2017 | 764936mE 7554051mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ | NA | | | | | | | | |
| MHDD 0025 | May 2017 | 761857mE 7553052mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ | NA | | | | | | | | |
| MHDD 0029 | June 2017 | 764930mE 7554056mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ | NA | | | | | | | | |

| | | | | | | | | | | | | | | | | | | | |
|---------------|----------------------|-----------------------|---|---|---|---|---|---|--|---|----|--|--|--|--|--|--|--|---|
| MHDD 0030 | May 2018 | 761940mE 7552963mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ | NA | | | | | | | | Minor recontouring of the drillpad is required. Holes (0030 – 0040) have been capped and space between 6 inch casing and 50mm DHEM casing has been filled with two part polyurethane foam. |
| MHDD 0031A | May 2018 | 761930mE 7552912mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ | NA | | | | | | | | See details re plugging MHDD0030 |
| MHDDH 0032 | May/ June 2018 | 761923mE 7553003mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ | NA | | | | | | | | See details re plugging MHDD0030 |
| MHDD 0033 | May 2018 | 764995mE 7554083mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ | NA | | | | | | | | See details re plugging MHDD0030 |
| MHDD 0034 | June 2018 | 761930mE 7552925mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ | NA | | | | | | | | See details re plugging MHDD0030 |
| MHDD 0021A | June 2018 | 761923mE 7552974mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ | NA | | | | | | | | See details re plugging MHDD0030 |
| MHDD 0035 | June 2018 | 761946mE 7552867mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ | NA | | | | | | | | See details re plugging MHDD0030 |
| MHDD 0037 | June 2018 | 761956mE 7552834mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ | NA | | | | | | | | See details re plugging MHDD0030 |
| MHDD 0038 | June 2018 | 761924mE 7552977mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ | NA | | | | | | | | See details re plugging MHDD0030 |
| MHDD 0039 | July 2018 | 761925mE 7552970mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ | NA | | | | | | | | See details re plugging MHDD0030 |
| MHDD 0040 | July 2018 | 762064mE 7552875mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ | NA | | | | | | | | Minor recontouring of the drillpad is required. See details re plugging MHDD0030 |

