**Rehabilitation Checklist – McArthur River Project Area, June 2018**

| Hole ID | Date Drilled | Drill hole Coordinates (GDA94 Lat\Long or GDA94 Zone # UTM) | Rehabilitation (✓ or date completed) | | | | | | | | | Post-closure Monitoring (2 Year after) | | | | | | | Sign off and Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Drill holes plugged/capped | Drill spoils buried/backfilled | Sample bags/core removed | Sumps backfilled | Topsoil/vegetation replaced | Drill pad ripped | Access track ripped | Rubbish removed | Is radiation within background levels? | Date of Monitoring | Is site nominated for ongoing monitoring? | Is the site revegetated? | Are there signs of erosion? | Are there weeds? | Is there subsidence? | Is radiation within background levels? | |
| 14MC DDH001 | 14/09/14 | 597375mE 8112575mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | X | ✓ | NA | Oct 2017 | YES | In progress | No | No | No | NA | |
| 14MC DDH002 | 23/09/14 | 594575mE 8108475mN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | X | ✓ | NA | Oct 2017 | YES | In progress | No | No | No | NA | |
| | | | | | | | | | | | | | | | | | | | |